

# **BUSHFIRE ATTACK LEVEL**

FOR FUTURE DWELLINGS AT STAGE 2 THE GARDENS MEDOWIE

Prepared by:

Firebird ecoSultants Pty Ltd ABN – 16 105 985 993

PO Box 354 Newcastle NSW 2300

 Mob:
 0414 465 990

 Ph:
 02 4910 3939

 Fax:
 02 4929 2727

 Email:
 sarah@firebirdeco.com.au





| Site Details:              | Stage 2 The Gardens Medowie NSW 2318                              |  |  |  |  |  |
|----------------------------|---|--|--|--|--|--|
| Prepared by:               | Sarah Jones B.Env.Sc.,G.Dip.DBPA (Design in Bushfire Prone Areas) |  |  |  |  |  |
|                            | Firebird ecoSultants Pty Ltd                                      |  |  |  |  |  |
|                            | ABN – 16 105 985 993  |  |  |  |  |  |
|                            | PO Box 354, Newcastle NSW 2300                                    |  |  |  |  |  |
|                            | M: 0414 465 990 Email: sarah@firebirdeco.com.au                   |  |  |  |  |  |
|                            | T: 02 4910 3939 Fax: 02 4929 2727                                 |  |  |  |  |  |
| Prepared for:              | McCloy Group  |  |  |  |  |  |
| Reference No.              | Medowie – McCloy Group  |  |  |  |  |  |
| Document<br>Status & Date: | September 2020  |  |  |  |  |  |

#### **Disclaimer**

Not withstanding the precautions adopted within this report, it should always be remembered that bushfires burn under a wide range of conditions. An element of risk, no matter how small always remains, and although the standard is designed to improve the performance of such buildings, there can be no guarantee, because of the variable nature of bushfires, that any one building will withstand bushfire attack on every occasion.



### **Executive Summary**

This report provides an assessment of the Bushfire Attack Level (BAL) at Stage 2 within The Gardens, Medowie in accordance with AS3959 (2018) *Construction of Buildings in Bushfire Prone Areas* Appendix A - Method 1. This report and mapping are not to be used to place wholesale restrictions on lots reflecting the resulting BAL mapping presented within. Future development of surrounding stages may result in lower BALs than detailed in this report.

This BAL report has shown that any future dwellings within the site will be able to meet the requirements of both AS3959-2018 and the PBP 2019 (NSW Rural Fire Service NSW).



Sarah Jones Ecologist / Bushfire Planner BPAD-A Certified Practitioner (BPD-PA-26512) B.Env.Sc., G.Dip.DBPA (Design for Bushfire Prone Areas)

#### Disclaimer:

The BALs as depicted within this report and mapping have been determined by management of vegetation to the east and south where land will be cleared for future stages. It should be noted that conditions may change over time that may result in different BALs for the lots.

Although every care has been taken in the preparation of this BAL Report, McCloy Group and the author accept no responsibility in errors in this report or damaged resulting from the information. It should be noted that upon lodgement of a Development Application (DA) with Council or Rural Fires Service they may recommend additional construction requirements (BALs).



# **Terms & Abbreviations**

| Abbreviation  | Meaning   |
|---------------|---|
| APZ           | Asset Protection Zone   |
| AS2419 -2005  | Australian Standard – Fire Hydrant Installations                            |
| AS3959-2018   | Australian Standard – Construction of Buildings in Bush Fire Prone<br>Areas |
| BAL           | Bushfire Attack Level   |
| BCA           | Building Code of Australia  |
| BPA           | Bush Fire Prone Area (Also Bushfire Prone Land)                             |
| BPL Map       | Bush Fire Prone Land Map  |
| BPMs          | Bush Fire Protection Measures   |
| EPA Act       | NSW Environmental Planning and Assessment Act 1979                          |
| FFDI          | Forest Fire Danger Index  |
| FMP           | Fuel Management Plan  |
| ha            | hectare   |
| IPA           | Inner Protection Area   |
| LGA           | Local Government Area   |
| ΟΡΑ           | Outer Protection Area   |
| PBP           | Planning for Bushfire Protection 2019                                       |
| PSC           | Port Stephens Council   |
| RF Act        | Rural Fires Act 1997  |
| RF Regulation | Rural Fires Regulation  |



## CONTENTS

| 1  | 1 INTRODUCTION |   |        |
|----|----------------|---|--------|
|    | 1.1            | Site Particulars  | 1      |
| 2  | METH           | ODOLOGY   | 2      |
|    | 2.1<br>2.2     | Vegetation Assessment<br>Slope Assessment                             | 2<br>2 |
| 3  | SITE A         | ASSESSMENT  | 3      |
|    | 3.1            | Vegetation and Slope Assessment                                       | 3      |
| 4  | BUSH           | FIRE ATTACK ASSESSMENT  | 4      |
|    | 4.1<br>4.2     | Bushfire Attack Assessment<br>Determination of Bushfire Attack Levels | 4<br>4 |
| 5  | CONC           | LUSION  | 7      |
| 6  | BIBLIC         | OGRAPHY   | 8      |
| AF | PENDIX         | X A SALE PLAN   | A-1    |
|    |                |   |        |

## TABLES

| Table 3-1: Vegetation & Slope Assessment    | 3 |
|---|---|
| Table 4-1: Bushfire Attack Level Assessment | 4 |

### **FIGURES**

| 6 |
|---|
|   |



## I INTRODUCTION

Firebird ecoSultants Pty Ltd has been engaged by McCloy Group Pty Ltd to undertake a Bushfire Attack Level (BAL) report for Stage 2 at The Gardens, Medowie hereafter referred to as the "site". Refer to Appendix A for Sales Plan.

This BAL report assesses the application of Australian Standard AS3959-2018 'Construction of Buildings on Bushfire Prone Land' and Appendix 1 of Planning for Bushfire Protection 2019 (PBP, 2019). AS3959 (2018) Appendix A – Method 1 has been used in this assessment.

This report has been prepared to provide guidance to prospective purchasers of what Bushfire Attack Levels (BALs) may be required for future dwellings within the site.

#### I.I Site Particulars

| Locality:            | Stage 2 at The Gardens, Medowie |  |  |  |
|----------------------|---------------------------------|--|--|--|
| LGA:                 | Port Stephens Council (PSC)     |  |  |  |
| Forest Danger Index: | 100                             |  |  |  |
| Current Land Use:    | Approved subdivision            |  |  |  |



## 2 METHODOLOGY

The Australian Standard for assessing the BAL and providing the detailed requirements for construction has been reviewed and amended with the latest version being adopted for use in bushfire prone areas of NSW in March 2020. This version is titled AS 3959-2018 'Construction of Buildings in Bushfire Prone Areas' (standards Australia 2018, was used in this assessment.

In addition, the NSW method of determining the bushfire attack level, found in Appendix 1 of the document 'Planning for Bushfire Protection 2019' (NSW Rural Fire Service 2019) has also been reviewed and amended to come into line with the process within AS 3959. Therefore, in NSW the methodology with AS 3959 is to be used to determine the bushfire attack level. AS3959 (2018) Appendix A – Method 1 has been used in this BAL assessment.

#### 2.1 Vegetation Assessment

Vegetation surveys and vegetation mapping carried out on the site has been undertaken as follows:

- Aerial Photograph Interpretation to map vegetation cover and extent.
- Confirmation of the vegetation assemblage typology present via a site inspection.

#### 2.2 Slope Assessment

Slope assessment has been undertaken as follows:

- Aerial Photograph Interpretation in conjunction with analysis of electronic contour maps with a contour interval of 10m.
- On site confirmation of slope measurements.



### **3 SITE ASSESSMENT**

A site inspection was undertaken on the site. The following assessment has been undertaken in accordance with the requirements of PBP (RFS, 2019) and AS3959-2018.

#### 3.1 Vegetation and Slope Assessment

An assessment of the slope affecting the bushfire behaviour was undertaken for a distance of 100m from the edge of the lot boundaries in the direction of the bushfire hazard. The slopes leading away from the site have been evaluated to identify both the average slope and by identifying the maximum slope present. These values help determine the level of gradient which will most significantly influence the fire behaviour of the site. Refer to Table 1 for Vegetation and Slope Assessment.

| Direction<br>from Site | Vegetation Classification                                      | Effective Slope |
|------------------------|--|-----------------|
| North                  | Land managed as an APZ until such time that development occurs | N/A             |
| East                   | Land managed as an APZ until such time that development occurs | N/A             |
| South                  | Land managed as an APZ until such time that development occurs | N/A             |
| West                   | Managed Land as part of Rural Residential lots                 | N/A             |

| Table 3-1: | Vegetation | & Slope | Assessment |
|------------|------------|---------|------------|
|------------|------------|---------|------------|



## 4 BUSHFIRE ATTACK ASSESSMENT

### 4.1 Bushfire Attack Assessment

To determine the bush fire attack and required Bushfire Attack Level (BAL) for the proposed subdivision the following steps were followed:

- 1. Determination of the vegetation types within 100m of the site, as assessed in section 3 of this report.
- 2. Determination of the distance between the vegetation and future dwellings has been assessed in section 4.2 of this report.
- 3. Determination of the effective slope as assessed in section 3 of this report.
- 4. A FFDI of 100 was determined for PSC LGA.

#### 4.2 Determination of Bushfire Attack Levels

The results from the above steps were used to calculate the required BAL in accordance with Method 1 of AS 3959 – 2018.


The results from this bush fire attack assessment are detailed below in Table 4-1– Bushfire Attack Level (BAL) Assessment and Figure 4-1 Bushfire Attack Level Map.

| Lot<br>Number | Vegetation<br>Type within<br>100m &<br>Direction<br>from future<br>dwellings | Average<br>Slope of<br>Land<br>(degrees) | Separation<br>Distance from<br>Identified<br>Vegetation | Bushfire<br>Attack Level<br>(BAL) | Construction<br>Section |
|---------------|--|--|---|-----------------------------------|-------------------------|
| 201           | Managed Land   | -  | >100 m  | BAL-LOW                           | N/A                     |
| 202           | Managed Land   | -  | >100 m  | BAL-LOW                           | N/A                     |
| 203           | Managed Land   | -  | >100 m  | BAL-LOW                           | N/A                     |
| 204           | Managed Land   | -  | >100 m  | BAL-LOW                           | N/A                     |
| 205           | Managed Land   | -  | >100 m  | BAL-LOW                           | N/A                     |
| 206           | Managed Land   | -  | >100 m  | BAL-LOW                           | N/A                     |
| 207           | Managed Land   | -  | >100 m  | BAL-LOW                           | N/A                     |
| 208           | Managed Land   | -  | >100 m  | BAL-LOW                           | N/A                     |



| Lot<br>Number | Vegetation<br>Type within<br>100m &<br>Direction<br>from future<br>dwellings | Average<br>Slope of<br>Land<br>(degrees) | Separation<br>Distance from<br>Identified<br>Vegetation | Bushfire<br>Attack Level<br>(BAL) | Construction<br>Section                      |
|---------------|--|--|---|-----------------------------------|--|
| 209           | Managed Land   | -  | >100 m  | BAL-LOW                           | N/A  |
| 210           | Managed Land   | -  | >100 m  | BAL-LOW                           | N/A  |
| 211           | Managed Land   | -  | >100 m  | BAL-LOW                           | N/A  |
| 212           | Managed Land   | Cross-slope                              | 45-<100m  | BAL-12.5                          | Sect 3 & 5 of AS3959<br>and Sect 7.5 of PBP. |
|               |  |  | >100 m  | BAL-LOW                           | N/A  |
| 213           | Managed Land   | -  | >100 m  | BAL-LOW                           | N/A  |
| 214           | Managed Land   | -  | >100 m  | BAL-LOW                           | N/A  |
| 215           | Managed Land   | -  | >100 m  | BAL-LOW                           | N/A  |
| 216           | Managed Land   | -  | >100 m  | BAL-LOW                           | N/A  |
| 217           | Managed Land   | -  | >100 m  | BAL-LOW                           | N/A  |
| 218           | Managed Land   | -  | >100 m  | BAL-LOW                           | N/A  |
| 219           | Managed Land   | -  | >100 m  | BAL-LOW                           | N/A  |
| 220           | Managed Land   | -  | >100 m  | BAL-LOW                           | N/A  |
| 221           | Managed Land   | -  | >100 m  | BAL-LOW                           | N/A  |
| 222           | Managed Land   | -  | >100 m  | BAL-LOW                           | N/A  |
| 223           | Managed Land   | -  | >100 m  | BAL-LOW                           | N/A  |

This report and mapping are not to be used to place wholesale restrictions on lots reflecting the resulting BAL mapping presented within. Building location and design will influence the application of the required BALs. For example, a lot indicated as being affected by BAL-29 may have those facades that are not exposed to the bushfire threat constructed to a lower BAL (i.e. BAL-19), reducing the costs of construction and providing more flexibility in choice of external building materials.








Client Stage 2 The Gardens Medowie 22 September 2020



Land to be managed as an APZ until development occurs

BAL 12.5

BAL Low



Level 1, 146 Hunter Street, Newcastle NSW 2300

#### Disclaimer

The BALS as depicted on this map have been determined by vegetation within 100m of Stage 2 at the time of the assessment in September 2020. It should be noted that conditions may change over time, that may result in different BALs for the site. Although every care has been taken in the preparation of this map the author accepts no responsibility for any misprints, errors, omissions, inaccuracies in these maps or damages resulting from the use of this information.

#### Ref No 2770

Firebird ecoSultants Pty Ltd ABN - 16 105 985 993 P O Box 354 Newcastle NSW 2300



for which it was supplied and in accordance with the terms of engagement for the commission.



## 5 CONCLUSION

This report provides an assessment of the Bushfire Attack Level (BAL) in accordance with AS3959-2018 Construction of Buildings in Bushfire Prone Areas for Stage 2 at The Gardens, Medowie.

This BAL report assesses the application of Australian Standard AS3959-2018 'Construction of Buildings in Bushfire Prone Land' and Appendix 1 of Planning for Bushfire Protection 2019 (PBP, 2019).

This report and mapping are not to be used to place wholesale restrictions on lots reflecting the resulting BAL mapping presented within. Future development of surrounding stages may result in lower BALs than detailed in this report.

This BAL report has shown that any future dwellings within the site will be able to meet the requirements of both AS3959-2018.



Sarah Jones Ecologist / Bushfire Planner FPA BPAD-A Certified Practitioner (BPD-PA-26512) B.Env.Sc. G.Dip.DBPA (Design for Bushfire Prone Areas)

#### Disclaimer:

The BALs as depicted within this report and mapping have been determined by vegetation within 100m of Stage 2 at the time of the assessment September 2020. It should be noted that conditions may change over time that may result in different BALs for the lots.



### **6 BIBLIOGRAPHY**

- NSW Rural Fire Service (RFS) 2019. Planning for Bushfire Protection: A guide for Councils, Planners, Fire Authorities, Developers and Home Owners. Australian Government Publishing Service, Canberra.
- Standards Australia. 2018. Construction of buildings in bushfire-prone Ares, AS3959, Fourth Edition 2018, Standards Australia International Ltd Sydney



# APPENDIX A SALE PLAN

